LANGLADE COUNTY U.S. PUBLIC LAND CORNER RESTORATION

U.S. PUBLIC LAND CORNER RESTORATION	
The West 1/4 corner of Section 19, T 32 N., R 9 E, Langlade 0	County, WI. E 1/4 cr Sec 24-32-8
Corner was: (check all that apply)	3208242000
Restored through acceptance of an obliterated evidence location.	
X Restored through acceptance of a found perpetuated location.	8
Determined to be lost and re-established through proportionate meth	nods.
Show bearings and distances to PLSS corners used for prop	portioning, and show original distances).
Restored/recovered/re-established in a location that differs from a pr	reviously established position.
(Show difference in plan view below).	
Check here if addition information is shown on the reverse side of the	is form.
Describe record evidence, recovered physical evidence, occupational evidence, testimonial evidence and all other evidence considered in the recovery/restoration of the corner.	
The original corner was established in 1851 by James M. Marsh. Original bearing trees: hemlock, 12", S10°E,	
42 lks., and a sugar, 10", N70°W, 28 lks. In July, 1918, W.C. Webly set a stone with "+" and surveyed the 1/4 line	
to the East. In 1921, Malcolm Hutchinson surveyed the 1/4 line to the East, but didn't describe this corner.	
In 1981, former surveyor Wm. Kelly found 6" x 6" granite stone for	
CONTROL OF THE PROPERTY OF THE	rner. 11/08/99 Dave Tlusty, Dean Williams found the 2" iron pipe
down 0.7' in the road and found one Kelly witness monument to	
as the best evidence of the corner location and perpetuated it as	shown below.
Physical description of the monument set: Left existing 2" iron pipe in place as found.	
Describe the accessories used to perpetuate the corner. In	
accessories found/set. Describe measuring point on beari	ng trees. Snow any topographic
features that would aid in future recovery of the corner.	Field book: FB18-13
LEGEND	
 ⊗ 3/4" x 30" rebar set flush ⑥ Kelly WM found (iron pipe with brass cap) 	
Ties measured electronically with Geodimeter	l voorti
Section line bearing assumed.	\NORTH/
·	
	I
3'± N74°02'33° W 81.27'	W 1/4 corner, Sec. 19
maple cluster	Found 2" iron pipe in road
Set white vinyl sign post @_N 88°44'03" W 33.02'	N 86°19'55" E 69.67'
Set white vinyl sign post O.5' south of this WM.	\$ 87°55'33"" E 33.88"
/	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
No. 3 to American	This rebar is in the center
A CONNE	of an old road to the east.
O CONTRACTOR OF THE PROPERTY O	nde nde
County C	ndex No
₹ 1	18. 18. 19. No.
Line with the control of the control	m \\
THEORIN COUNTY SEE THE	RECEIVED AT
AUT SIH O	
ACTION SOLVER STATE OF THE STAT	70
The state of the s	70

Virele (1.6.4)

I, David E. Tlusty, Registered Land Surveyor, as Langlade County Surveyor, certify that the corner location on this record was determined by me and that this U.S. Public Land Survey Monument Record is correct to the best of my knowledge and belief.

SW corner, Sec. 19 Set Berntsen SN-1 nail ○ = corner perpetuated
The West 1/4
corner of Section 19,
T. 32 N., R. 9 E.,
Langlade County, WI

P1 32-09