



Part of
GOV'T. LOTS 4,5,&6
SECTION 18, T31N, R7E
 Lincoln County, Wis.



solar bearings

- iron mont found in place
- stone mont found in place
- iron pipe set



Scale 1"=200'
 September, 1972
 REVISED: December 1972

Northwoods Surveyors, Inc.
Robert H. Winat
 Land Surveyor 5-1049

RECEIVED AT LINCOLN COUNTY
 COURTHOUSE THIS 18th DAY
 OF Jan 1973
Osman Odigwed
 TAX DESCRIPTION

Meander Corner
 erroneous iron pipe
 N75-07W, 89'

Meander Corner

erroneous iron pipe
 N88-08E, 72.0'

MISA

