RECEIVED AT LINCOLN COUNTY
COURTHOUSE THIS 1844 DAY
OF August 2003
Tomy Dall
LAND INFORMATION OFFICE

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

NOTE: THIS FORM IS INTENDED AND DES LAND SURVEY MONUMENT RECORD (3) (a) WITH SAID REQUIREMENTS.	IGNED TO FULFILL ALL (b) (c) (d) (e) (f)	REQUIREMENTS (g) (h) (i).	OF WISCONSIN ADMINISTRATIVE COL AN ADDITIONAL SHEET MAY BE ADDI	DE, CHAPTER ED IF NECESS	A-E 7.08 U.S. PUBLIC ARY TO CONFORM
(a) CORNER LOCATION.	TOWNSHIP _	32	NORTH		
	RANGE	5	_EAST/ WEST	2	2
TOWN/CITY/VILLAGE	HARDING			3	3 1 h
COUNTY	LINCOLN			,	N
X-X-X-X-X-X-X-X-X-X-X-X-X-X-X-X-X-X-X-			·	SECTION 3	

(b) (f) (g) (h) DESCRIPTION OF MONUMENT FOUND AT THIS CORNER AND IF IT WAS ACCEPTED, STATE ALL EVIDENCE (MATERIAL, TESTIMONIAL, OCCUPATIONAL, PLATS, RECORDS, OTHER MONUMENTS) USED AS BASIS FOR ACCEPTING. IF NOT ACCEPTED OR IF NOTHING WAS THROUGH LOST CORNER PROPORTIONATE METHODS, INDICATE ALL MONUMENTS, DISTANCES AND DIRECTIONS USED TO ESTABLISH. INDICATE TYPE OF MONUMENT FOUND OR SET AND

USING BACKHOE PROVIDED BY COPPER RIVER DEVELOPMENT COMPANY, ALAN KOEHLER, OPERATOR, WE DUG AND FOUND A 6" x 6" GRANITE STONE MONUMENT, IN TWO PIECES. NONE OF THE STONE PIECES HAD AN X ON TOP. IT LOOKED LIKE STONE HAD BEEN HIT BY GRADER MANY TIMES. STONE WAS ABOUT 3 FEET BELOW ROAD SURFACE. ROAD HAD BEEN SAND LIFTED ABOUT 2 FEET. HELD LONGER PIECE OF MONUMENT, STILL IN UPRIGHT POSITION AS CORNER LOCATION. SET A BERNTSEN MONUMENT FOR CORNER, LEAVING GRANITE STONE PIECES IN HOLE. WHEN WE SET THE BERNTSEN MONUMENT (AFTER BACK FILLING), WE BROKE THE BOTTOM PART OF BERNTSEN OFF (HIT GRANITE MONUMENTS) BERNTSEN IS ABOUT 8" BELOW ROAD SURFACE. DISTANCES TO IRON PIPES AT 40 LINE TO WEST, AND TO S 1/4 CORNER OF SEC. 33 LOOKED GOOD. HELD AS CORNER.

(c) (d) (e) PLAN VIEW OF CORNER WITH TIES TO AT LEAST 4 WITNESS MONUMENTS. IF IN DISAGREEMENT WITH PREVIOUSLY ESTABLISHED CORNER, SHOW THE DISTANCES BETWEEN THE TWO CORNERS AND ALSO INDICATE THE TIES TO THE DISPUTED CORNER.







