Attachment to Tie Sheet G-09, T32N, R7E 43207082000

I visited the corner on 7/24/2018 to verify the corner and reference tie monumentation. I found the Granite monument and all 4 ties from David Renaud (REI) tie sheet (11/29/2002). The established Coordinates and all 4 ties agree with existing monument.

Anthony R. Dallman, PLS-2405

Lincoln County Surveyor

U.S. PUBLIC LAND	SURVEY MONU	JMENT RECORD
Note: This form is intended and designed to for Public Land Survey Monument Record (3) conform with said requirements.	ulfill all requirements of Wisconsin Adm)(a)(b)(c)(d)(e)(f)(g)(h)(i). An additiona	ninistrative Code, Chapter A—E 5.02, U.S. I sheet may be added if necessary to
(a) Corner location: Township 32	_North	
Range7Ec	ast	8—————————————————————————————————————
Town/City/Village MERRILL		
CountyLINCOLN		Section <u>8</u>
(h)(f)(a)(h) Description of manument for	und at this corner and if it was	
(b)(f)(g)(h) Description of monument found at this corner and if it was accepted, state all evidence (material, testimonial, occupational, plats, records, other monuments)used as a basis for accepting. If not accepted or if nothing was found, state evidence used as basis for establishing location. If reestablished through lost corner proportionate methods, indicate all monuments, distances and directions used to establish.		
FOUND 6" x 6" SCRIBED GRANITE ACCEPTED THIS AS THE CORNER SET TIES TO PERPETUATE CORN	R LOCATION.	VEY NOTES. WE
		DAT LINCOLN COUNTY OUSE THIS 310 DAY
		ember 2002
	Tany	Dalle
LAND MFORMATION OFFICE		
(c)(d)(e) Plan view of corner with ties to at least 4 witness monuments. If in disagreement with previously established corner, show the distances between the two corners and also indicate the ties to the		
d'anulad annua	3" MAPLE	
	HARDWOODS	COORDINATES ARE REFERENCED TO THE LINCOLN COUNTY COORDINATE SYSTEM AS DEVELOPED BY THE WISCONSIN DEPARTMENT OF TRANSPORTATION AND WERE DETERMINED BY GPS OBSERVATIONS ON CONTROL POINTS AS SUPPLIED BY LINCOLN COUNTY.
		BEARINGS ARE REFERENCED TO MAGNETIC NORTH.
6" TWIN MAPLE & CONTROL NOW NOW NOW	\$88°E	
11.15'	15.75' \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	.E
NORTH	N 155925.5883 E 407304.8520	
	21.34'	○ - SET 3/4" x 30" REBAR W/ ALUM CAP 1' FROM BEARING TREE
		- EAST 1/4 CORNER FOUND 6" x 6" GRANITE STONE
NOT TO SCALE		
	8" MAPLE	S C O N on linde
(i) I, David A. Radenz, RLS certify that was determined by me or under me this U.S. Public Land Survey Monuncomplete to the best of my knowledge.	y direction and control and that nent Record is correct and	
Signature	Date	- RA A CONSTRUCTION OF THE PROPERTY OF THE PRO

