U.S. PUBLIC LAND SURVEY MONUMENT RECORD

NOTE: THIS FORM IS INTENDED AND DESIGNED TO FULFILL ALL REQUIREMENTS OF WISCONSIN ADMINISTRATIVE CODE, CHAPTER A-E 7.08, U.S. PUBLIC LAND SURVEY MONUMENT RECORD (3)(a)(b)(c)(d)(e)(f)(g)(h)(i). ADDITIONAL SHEETS MAY BE NECESSARY TO CONFORM TO SAID REQUIREMENTS.

(a) CORNER LOCATION:

MEANDER CORNER, SECTION 12
TOWNSHIP 35 NORTH
RANGE 6 EAST
TOWN OF BRADLEY
LINCOLN COUNTY
WISCONSIN

(b) HISTORY OF ORIGINAL CORNER:


ORIGINAL SURVEYOR: JOHN H. FISHER, 2" PIPE

COMMENCING DATE:

COMPLETION DATE: MARCH 25, 1978

ORIGINAL BEARING TREES:

6" Norway Pine; N 66° W, 8.7'



(f)(g)(h) DESCRIPTION OF MONUMENT FOUND AT THIS CORNER AND IF IT WAS ACCEPTED. STATE ALL EVIDENCE (MATERIAL, TESTIMONIAL, OCCUPATIONAL, PLATS, RECORDS, OTHER MONUMENTS) USED AS A BASIS FOR ESTABLISHING LOCATION. IF RE-ESTABLISHING THROUGH LOST CORNER PROPORTIONATE METHODS, INDICATE ALL MONUMENTS, DISTANCES, AND DIRECTIONS USED TO ESTABLISH. INDICATE TYPE OF MONUMENTS FOUND OR SET.

11/04/1992, Lester Schmit accepted 2" Iron Pipe for a property survey.

7/12/1993, David Osterbrink accepted 2" Iron Pipe for a property survey.

4/19/1995, James D. Rein accepted 2" Iron Pipe for a property survey.

02/102022, Todd Loftus accepted 2" Iron Pipe for a property survey.

7/20/2023, I, Anthony R. Dallman, PLS-2405, found a 2" Iron Pipe pulled out and stuck in uprooted tree roots. I used nearby survey monuments to re-establish the corner position to reset the 2" Iron Pipe, accepted this location and set witness monuments, as shown in the sketch below, to further perpetuate the corner location.

(c)(d)(e) PLAN VIEW OF THE CORNER WITH TIES TO AT LEAST FOUR WITNESSES. IF IN DISAGREEMENT WITH PREVIOUSLY ESTABLISHED CORNER, SHOW THE DISTANCES BETWEEN THE TWO CORNERS AND ALSO THE TIES TO THE DISPUTED CORNER.

- Tie bearings by hand-held compass.
- Tie distances by steel tape.
- Not to scale.

