



BT^s
 asp 10' N 7° E 38.98'
 FB 9' N 67° E 10.25'
 elm 3' S 82° E 66.68'
 FB 7' S 76° E 22.90'

BT^s
 FB 8' S 23° W 27.80'
 MH 10' N 44° W 20.01'
 MH 10' N 3° E 32.16'
 twin BY 8' N 64° E 19.16'

NE 22
 BT^s
 asp 12' N 85° E 29.21'
 asp 12' N 51° E 26.88'
 PW 10' N 60° W 46.91'
 PW 12' N 40° W 42.62'

NE 23
 (found)
 BT^s
 oak 7' N 46° W 38.90'
 basswood 15' S 36° W 35.50'
 asp 10' N 55° E 42.56'
 oak 6' S 88° E 33.82'


CN 1/16
 BT^s
 PN 9' S 73° W 38.92'
 asp 9' N 4° E 9.69'

E 1/4
 BT^s
 MR 3' S 90° W 24.31'
 twin PW 12' N 37° W 26.28'
 asp 12' N 59° E 38.35'
 MR 4' S 61° E 30.13'

S 1/4
 BT^s
 asp 12' N 42° W 100.33'
 ash 3' N 10° W 52.82'
 asp 4' S 15° W 62.94'
 P. pole S 64° W 123.78'

Ref.
 P. pole S 38° E 30.98'
 P. pole N 81° W 51.70'
 i.p. S 47° W 51.50'
 i.p. N 12° E 182.04'

SW 22
 Ref.
 i.p. S 47° E 53.35'
 P. pole South 36.58'
 i.p. N 21° W 61.52'
 sign post N 28° E 62.60'



LEGEND

- ⊕ Lincoln Co. Berntsen aluminum, set
- 1" iron pipe, set
- 1" iron rod, set
- ⊙ PK nail set (a more permanent monument to be set later)

NOTES

Survey for the Wisc. Dept. of Natural Resources
 Antigo Area Hdqtrs., M. Schmeiser, Land Agent
 Field survey completed 10/25/87.
 Field notes filed at D.N.R. Trout Lake Sta., Boulder jct.
 Tie points in BT^s & P. poles are nails on side.



I, M.E. Seymour, RLS 1412 certify this to be a correct representation of Sec. 22 to the best of my knowledge and belief.
Marvin E. Seymour Oct. 15, 1987

SECTION SUBDIVISION
 T 32N, R 7E, Lincoln Co.
 Sec. 22

L103
 Scale 1" = 300'
 Dr. by M. Seymour 10/14/87