



- = 2" iron pipe found in place
- = Square iron cap found in place
- = 1" iron pipe found in place
- = 2" iron pipe set
- = 3" iron pipe set
- = 1 1/2" iron rod set

Note:
 Records 1, 2 and 3 do not meet the requirements set forth in Chapter 19.05 of the Wisconsin Administrative Code and will require extensive site preparation prior to installation of any advanced systems for septic tank effluent disposal.

COUNTY
 1/8 CORNER
 PK 140.0 IN DIAMETER 1982
 S 40° E 376
 1000 P.D.
 S 73° E 300

TRUNK HIGHWAY
 1322.0
 S 88° 45' N

The
 NE 1/4 of the SE 1/4
 and the
 SE 1/4 of the SE 1/4
 SECTION 9, T34N, R5E
 Tomahawk Township
 Lincoln County, Wisconsin

RECEIVED AT LINCOLN COUNTY
 COURTHOUSE THIS 13 DAY
 OF June 19 75.
Pat Pruebs
 TAX DESCRIPTION OFFICE

Scale 1" = 100'
 April, 1974

Northwoods
 Surveyors
 Inc.
John H. Herber
 Land Surveyor

SECTION 9
 T34N
 R5E
 KOHL ROAD
 JAECKS ROAD

RECEIVED AT LINCOLN COUNTY
 COURTHOUSE THIS 13 DAY
 OF June 19 75.
 TAX DESCRIPTION OFFICE

LIB