


LS9A



John H. Fisher, Registered Land Surveyor 5-836 hereby
certify that we have surveyed the property shown hereon, that
this map is a true and accurate representation thereof, that
survey was performed by order of Donald Olson, and that we
have complied with applicable requirements of s. A-E 501
of the Wisconsin Administrative Code.

John H. Fisher
John H. Fisher R.L.S. 5-836
dated Mar. 24, 1980

John H. Fisher & Associates, Inc.
Minocqua, Wisconsin

RECEIVED AT LINCOLN COUNTY
COURTHOUSE THIS 30th DAY
OF January 19 1981.
Joe Druwe
TAX DESCRIPTION OFFICE

REPORT OF SURVEY
11/25/80

Goes with
A.P. Survey
on other side

On May 18, 1979 we gave Mr. Ken Worden an estimate to survey 3 lots on Squaw Lake (Lots 8, 9, 10, 11 and 12 of Thielers Squaw Lake Subdivision being an unrecorded plat). We explained that we would base the survey on the East-West one-quarter line as established by Rhipelander Paper Company (R.I.P.C.O.) due to the fact that the north line of Lot 12 is shown on Thielers Subdivision as being the one-quarter line.

In early June, 1979 we did the field work to reestablish the East-West one-quarter line between R.I.P.C.O.'s Center of Section and the West one-quarter corner. We found that the actual one-quarter line fell 37.42 feet south of the line as marked by Sayers when he did the unrecorded plat, which alerted us to the fact that Sayers had established the East-West one-quarter line incorrectly. Since the Sayers plat is an unrecorded plat, the metes and bounds descriptions must be used in relocating the necessary corners. Therefore by using the true one-quarter line and the appropriate metes and bounds descriptions the lots would end up 37.42 feet south of the lines which all neighbors have been living to.

Realizing that this would create many problems in the neighborhood we approached Mr. Worden and suggested asking the Town of Harrison to order an Assessor's Plat of the subject lots pursuant to Chapter C.27 of the State Statutes. Mr. Worden talked to the other people involved in this survey, who agreed and we then approached the Town with our request. On December 5, 1979 the Town of Harrison ordered an Assessor's Plat of Lots 8, 9, 10, 11 and 12 of the unrecorded plat of Thielers Squaw Lake Subdivision.

We then proceeded by staking the lot corners using the original Sayers map and monuments pointed out by Mr. Worden. We used this information to try to set the lines at their original location as shown on the Thielers Subdivision map. One other discrepancy was found while staking the lots; the road was not built in the location as shown on the original map. Therefore we extended or shortened the lines to meet the existing road right-of-way as shown on the attached map. Next we sent a preliminary map and letter of explanation to all property owners and adjacent property owners explaining the assessor's plat procedure.

We received a call from the property owner north of the subject plat expressing concern about losing 37.42 feet from his lot if he agreed with this plat. We explained the situation and suggested contacting his northerly neighbor about a line by agreement or being included in this assessor's plat. His neighbor did not want to get involved, therefore he filed an objection to the Plat.

After many months of correspondence the people who approached us decided to forget the whole survey to avoid any conflicts with any neighbors. We then pulled the pipes that were shown on this map and are about to approach the Town asking them to cancel their order.

Alan Drum Associates, Inc.
Alan C. Drum

Sheldon D. Schwark
Sheridan D. Schwark

LS9C

LS9A