CE 1/16 Cor., C 1/4 Cor., Sec. 32 Sec. 32 East-West 1/4 Line S 89°54'20" E 1313.92 PARCEL "B" North-South 1/4 PARCEL "A" N 89° 57'06" W 1318.82 South 1/16 Line CS 1/16 Cor., Sec. 32 C 1/16 SE Cor., Sec. 32 S 1/4 Cor., Sec. 32

NW 1/4, of the SE 1/4
SECTION 32

T. 35 N., R. 7 E.

Town of King
Lincoln County, Wis.

I, Lester J. Schmit, Registered Land Surveyor S-1192 hereby certify that I have surveyed the property shown hereon; that this map is a true and accurate representation thereof; that said survey was performed by order of Thomas Loka; and that I have complied with applicable requirements of s. A-E 7 of the Wisconsin Administrative Code.

Note: Legal descriptions, if any, conforming to this survey have been provided on separate sheets.

Lester J. Schmit R.L.S. S-1192

Dated this 10m day of September 1987

On 16 May 2001, I found the CentreEast 1/15 and the Centre 1/16 Southeast corners had been disturbed by reconstruction of Gliff Road. I relocated these 2 corners in the proper position. The iron pipe at 307.19' northerly along the east 1/16 line from said Centre 1/16 Southeast corner was removed and I reset same, for Tom Loka.

LEGEND

- BERNTSEN MONUMENT FOUND IN PLACE.
- I IRON PIPE FOUND IN PLACE.
- O JI/4" IRON PIPE SET THIS SURVEY.

BEARINGS SOLAR

RECEIVED AT LINCOLN COUNTY

COURTHOUSE THIS 13TH DAY

OF September 20 01

Tony Dalle

SE Cor TIMBERI AND SURVEYORS IN

NO SURVEY

TIMBERLAND SURVEYORS, INC. TOMAHAWK WIS.

SURVEY FOR

THOMAS LOKA

N9699 CLOVERBELT RD.

TOMAHAWK, WIS.

DATE 10 MAY 83 DWN. BY L.J.S. SCALE 1"=100"

REVISED

BY L.J.S.

BY

B

494