

○ = Iron rod found in place
 ● = Iron pipe found in place
 * = Nail set
 **** = Fenceline

Bearings Magnetic

SPIRIT
FLOWAGE

Part of the
 NE 1/4 of the SW 1/4
 and
 SE 1/4 of the SW 1/4
 SECTION 8, T34N, R5E
 Lincoln County, Wis.




Scale 1" = 100'
 April, 1970

RECEIVED AT LINCOLN COUNTY
 COURTHOUSE THIS 1st DAY
 OF March 1970
Oscar O. Dequard
 TAX DESCRIPTION OFFICE

Northwoods Surveyors Inc.
John H. Fisher
 Land Surveyor

NEW WOOD ROAD



MIA

11111-8-345

H. Beby