


NW 1/4, of the SE 1/4
 and the
 SW 1/4, of the SE 1/4
SECTION 5
T. 33 N., R. 6 E.
 Town of Rock Falls
 Lincoln County, Wis.

NOTES

- 1) Dimensions on this survey and map are generated from a Section Summary by Keith J. Walkowski, S-2717 and filed with the Lincoln County Land Information Office on 9 March 2006.
- 2) Steel fence posts set along north-south 1/4 line and east-1/16 line at random locations.

CS 1/16 Cor., Sec. 5'
 Iron pipe is N49°15' E, 0.85'
 from actual corner location.

S 1/16 SE Cor., Sec. 5
 Iron pipe is N71°11' W, 1.70'
 from actual corner location.



LEGEND

- ⊙ BERNTSEN MONUMENT FOUND IN PLACE.
- 6" SQUARE GRAY GRANITE MONUMENT FOUND IN PLACE.
- 1 3/8" O.D. IRON PIPE FOUND IN PLACE.
- ⊙ 1 3/8" O.D. IRON PIPE SET THIS SURVEY.
- ⊠ MAG NAIL SET THIS SURVEY.

I, Lester J. Schmit, Registered Land Surveyor S-1192 hereby certify that I have surveyed the property shown hereon; that this map is a true and accurate representation thereof; that said survey was performed by order of John E. Johnson; and that I have complied with applicable requirements of s. A-E 7 of the Wisconsin Administrative Code.

Note: Legal descriptions, if any, conforming to this survey have been provided on separate sheets.

Lester J. Schmit
 Lester J. Schmit R.L.S. S-1192
 Dated this 29th day of October 2007

RECEIVED BY LINCOLN COUNTY
 SURVEYOR THIS 1ST DAY
 OF August 2008
Tom Dell
 COUNTY SURVEYOR

TIMBERLAND SURVEYORS		<small>TOMAHAWK WIS.</small>
SURVEY FOR		
JOHN E. JOHNSON		
W 5338 ROW RD.		
MERRILL, WIS. 54452		
DATE 29 OCT 07		DWN. BY L.J.S. SCALE 1" = 200'
REVISED	BY	DWG. NO.
REVISED	BY	1350

