



- ⊙ = 3/4" iron pipe found in place.
- = 1" iron pipe found in place.
- ⊖ = 1 1/4" iron pipe found in place.
- ⓪ = 2" iron pipe found in place.
- = 1/4" steel post found in place.
- = 1 1/4" iron pipe set.
- = 2" iron pipe set.
- ▨ = existing building

Part of the
SE 1/4 of the NW 1/4
SECTION 31, T35N, R6E

Bradley Township
 Lincoln County, Wisconsin

RECEIVED AT LINCOLN COUNTY
 COURTHOUSE THIS 19 DAY
 OF June 1975.
Pat Rieker
 TAX DESCRIPTION OFFICE

Northwoods
 Surveyors
 Inc.



I, JOHN H. FISHER, Registered
 Land Surveyor # S-836, hereby certify that
 I have surveyed the property shown hereon; that
 this map is an accurate survey of said property
 to the best of my knowledge and belief; that I
 have performed this survey by order of Mr and
 Mrs. James Whipple, and that I have complied
 with the applicable requirements of Wisconsin
 Administrative Code s. A-E 5.01.

John H. Fisher
 Dated this 26 day of February, 1975
 K. Gieseler

NOTE: legal description conforming to this survey has been provided on a separate sheet.

RECEIVED AT LINCOLN COUNTY
 COURTHOUSE THIS 19 DAY
 OF June 1975.
Pat Rieker
 TAX DESCRIPTION OFFICE

Scale 1" = 100'