O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION

Index No. <u>C -21</u>

History of original corner establishment:

Monument: Wood Post Date: October, 1852

Surveyor: Richard Chaney

Witnesses: 10" Hemlock N4OE 23 links 9" Hemlock S54W 33 links

(Register of Deeds)

Description of corner evidence found:

A 6" by 6" red granite monument found in place at a fence intersection was 15 inches above grade. Writing on stone can be read facing south. The stone was set in 1903 by Louis Kleinschmidt. His map is on record in the Lincoln County Register of Deeds Office.

Description of monument and accessories I established to perpetuate the original location of this corner. 1 = 6" x 6" RED GRANITE MONUMENT FOUND 15' 585W, 12.68 6" DOUBLE BALSAM P. K. NAILS SET IN BLAZED BEARING 8.90 TREES 3.12 5" POPLAR Dated at Wausau , Wis., this 30th day of July 19 79 Signature Shundan Schwark Title Registered Land Surveyor Registration No. S-1205 (County Surveyor, Registered Land Surveyor, or other duly authorized official) Office of Register of Deeds, County of......, I hereby certify that the within instrument was filed in this office for record on the day of 19

..Deputy