O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION

Index No. U-/

History of original corner establishment:

Notes of the original government survey indicate wood posts were set at all section and quarter-section corners. Stone monuments subsequently were placed at these corners during remonumentation surveys.

Description of corner evidence found:

Excavated roadway with backhoe. At depth of 6 inches below gravel roadway surface a 6"x8"x33" Limestone monument was recovered. Top had been shattered and monument was tipped slightly to South. Top 10 inch piece was still in place but fractured. Bottom 23 inches of stone were in excellent shape, hence a new chisel "X" was cut into center top. Monument was straightened and temporary ties taken. Bottom 23 inch segment was reset in original location such that top is positioned 5 inches below roadway surface. Set 1"x36" iron pipe along North side of monument to aid future location.

Description of monument and accessories I established to perpetuate the original location of this corner.

See sketch on reverse



Dated at Schofield	, Wis., this	2nd	day of	June	
Signature La Verne 71. Most (County Surveyor, Region	her Title 1	Registered	Land Surv	evor Regis	
Office of Register of Deeds, County of instrument was filed in this office for at	of record on the		day of	, I hereby o	ertify that the within
(Register of De	eeds)		-		
By		Deputs	,		

