



CERTIFIED LAND CORNER RESTORATION

Index No. E-9

State of Wisconsin }  
 County of Lincoln } ss.

History of original corner establishment:  
 Wood post set by original government surveyor

I Sheridan D. Schwark, do hereby certify that on the 17th day of August, 1982, I found evidence of the Southwest corner of Section 4 Township 32, North, Range 8, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.



Description of corner evidence found:

We excavated the blacktop road at the intersection of the two centerlines, Jack Prueser backhoe operator, and found a 6" x 6" red granite monument about 2 feet below the surface. The monument was tipped northeasterly. We replaced the monument with a Lincoln County Berntsen monument and established the references as shown below.

Resident witnesses:

.....  
 .....  
 .....

Description of monument and accessories I established to perpetuate the original location of this corner.



Dated at Merrill, Wis., this 23rd day of August, 1982

Signature Sheridan D. Schwark Title Registered Land Surveyor Registration No. S-1205  
 (County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of \_\_\_\_\_, I hereby certify that the within instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19\_\_\_\_ at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

(Register of Deeds)

By \_\_\_\_\_ Deputy

○ = Corner monument restored.