

CERTIFIED LAND CORNER RESTORATION

Index No. 0-21

State of Wisconsin }
County of Lincoln } ss.

History of original corner establishment:

Date of Original Survey: June 1861
Survey performed by: Alfred Millard - Deputy Surveyor

Witnesses: 12" Hemlock, N65°E, 14 Links
7" Hemlock, S55°W, 12 links

I John H. Fisher do hereby certify that on the 19 day of June, 1979, I found evidence of the south west corner of Section 25 Township 35, North, Range 7 E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:

Old fence bearing north and south and stream to south, used fence and original distance from creek as direct witness.

Resident witnesses:

none

Description of monument and accessories I established to perpetuate the original location of this corner.

Set Lincoln County Berntsen Monument

Witnesses: 4" Double Maple, S58°W, 12.0 feet
6" Poplar, S28°W, 14.6 feet
4" White Birch, S74°W, 29.8 feet
8" Norway Pine, N14°E, 33.6 feet



○ = Corner monument restored.



Dated at Minocqua, Wis., this 29th day of June, 1979.

Signature John H. Fisher Title Registered Land Surveyor Registration No. S-836
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy