O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION

Index No. Z - 15

History of original corner establishment:

Date: March, 1852

Surveyor: A.G. & F.S. Ellis

Monument: Wood post

Witnesses: 12" Pine S37°E 30 links 16" " N80°W 77 "

Description of corner evidence found:

We found a l" solid steel bar in the intersection of California and Water Street which fit the ties on record at the City Engineer's office. The ties had been filed by Becher-Hoppe Engineers of Schofield, Wisconsin. We contacted Don Frisque (R.L.S.) manager of Land Survey Department for Becher-Hoppe, to ask if he wanted to tie in corner. He said we should go ahead and tie it in. While digging the l" steel bar out, we found a stone monument below the bar with a drill hole in the top. This was the same type of stone that we've found in other areas in the Town of Scott, set by Louis Kleinschmidt in 1903.

Description of monument and accessories I established to perpetuate the original location of this corner.

We set a Lincoln County Berntsen monument with the following witness monuments: the south side of the base of a stop sign bearing, N25°W 45.09'
P.K. nail set in telephone pole bearing N61°E 52.67'
P.K. nail set in power pole No. 128 ccl-259-66, bearing S53°E 36.21'
center top of fire hydrant No. 259, bearing S43°E 31.42'
1 1/4" iron rod bearing South, 33.00'

Dated at Merrill , Wis., this	14.th da	y of April	1978
Signature Shrudan D. Schwork Title F (County Surveyor, Registered Land Survey	legistered La	nd SurveyorRe	gistration NoS-1205
Office of Register of Deeds, County ofinstrument was filed in this office for record on theato'clock		I hereby	certify that the within
(Register of Deeds)			
By	D		