
Resident witnesses:



O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION

Index No. M - 5

History of original cornersestablishment:

Date: March, 1852

Surveyor: A.G. & F.S. Ellis

Monument: Wood Post

Witnesses: 18" Sugar Maple, N42°E, 8 links 18" Birch, S25°W, 44 links

Description of corner evidence found:

We excavated the road intersection and found a 6" x 6" stone monument approximately 2.5 below the road surface. It appears that the top of the stone was broken off. because the stone was not as long as ones we had found previously in the Town of Scott. The stone monuments were set in 1903 by Louis Kleinschmidt (Land Surveyor) There is a map of his resurvey in the Register of Deeds office in the Courthouse.

Description of monument and accessories I established to perpetuate the original location of this corner.

We set a Lincoln County Berntsen Monument above the stone having the following witness monuments:

1 1/4" x 30" solid round iron rod set approximately 3' North of Joe Snow, Snow Hill Road sign bearing N37°E, 41.79'

1 1/4" x 30" solid round iron rod set approximately 3' East of stop sign bearing S35°W, 36.97'
1 1/4" x 30" solid mound iron rod set approximately 3' North of guy pole
No. 3106-19El bearing S48°W, 37.10'

1 1/2" iron pipe found in place approximately 3' Northeast of power pole No. 3106 -18R15 bearing N42°W. 35.88'

Dated at Merrill , Wis., this 23 rd day of June , 19.78

Signature Sheridan D. Schwork TitleRegistered Land Surveyor Registration No. S-1205 (County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of......, I hereby certify that the within at......o'clock...... M.

(Register of Deeds)

By......Deputy