
I established a new monument and accessories as described hereon to perpetuate the original

Resident witnesses:

location of this corner.



O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION

Index No. M-25

History of original corner establishment:

Date: July 1851

Surveyor: James M. Marsh

Monument: Wood Post

Witnesses: 14" Birch, 542E, 58 links 14" Birch, S28W, 33 links

18" Hemlock, N74°W, 34 links 12" Hemlock, N55°E, 37 links

Description of corner evidence found:

We found two existing ties which were set by Francis Fox, R.L.S., according to Al Neumann, who worked with Francis Fox. We extended the line between the two monuments to the centerline of C.T.H. "G". The distance from the closest monument fit 50' well. We dug and found a 6" x 6" red granite monument, upright, approximately 2' below grade. We set 3 - 6" Lincoln County Berntsen Monument extentions with a cap above the granite monument.

Description of monument and accessories I established to perpetuate the original location of this corner. 13' SOUTH OF = 3/4" x 30" IRON POWER POLE 13' WEST OF SET 2" AXLE SHAFT THERE IS A I" FOUND IN PLACE LRON PIPE ON WEST SIDE OF AKLE SHAFT " LINCOLN COUNTY WEST BERNTSEN MONUMENT 49.68 - POWER POLE 74.95 26th U Dated at Merrill Wis., this...... day of November 19 79 Signature Sheridan D. Schwak Title Registered Land Surveyor Registration No. S-1205 (County Surveyor, Registered Land Surveyor, or other duly authorized official) Office of Register of Deeds, County of......, I hereby certify that the within at.....o'clock............ M. (Register of Deeds)