 - - -		 	
 -	32	 	
 - -	!-	 	
1	1	1	

O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION

Index No. W-9

History of original corner establishment:

Date: April, 1852

Surveyor: A.G. & F.S. Ellis

Monument: Wood post

Witnesses: 15" Hemlock N21°W, 13 links 20" Pine N12°E, 5 links

Description of corner evidence found:

A 1" iron pipe was found. The pipe was set in 1972 by Robert Winat, Registered Land Surveyor. Oscar Osness, local resident and town chairman had informed him that the road had been previously bulldozed to old grade and no monument was found.

Description of monument and accessories I established to perpetuate the original location of this corner.

We set a Lincoln County Berntsen monument with the following witness monuments:

1" x 30" iron pipe set 1' from telephone pole No. 3207-33L1 bearing N50°E, 40.48'

1" x 30" iron pipe set S58°E, 28.40'

1" x 30" iron pipe set S58°E, 28.40'

1" x 30" iron pipe set 1' from Sunset Lane sign bearing S50°W, 41.88'

1" x 30" iron pipe set 1' from Dead End sign bearing N59 W, 33.76'







