


CERTIFIED LAND CORNER RESTORATION

Index No. E-15

State of Wisconsin }  
County of LINCOLN } ss.

I Sheridan D. Schwark, do hereby certify that on the 6 th day of October, 19 80, I found evidence of the North one-quarter corner of Section 10 Township 32, North, Range 8 East, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:



○ = Corner monument restored.


History of original corner establishment:

Wood post set by original government surveyor.

Description of corner evidence found:

We found a 30" long red granite monument with a 6" x 6" square top and an irregular shaped bottom. The monument was obviously heaved upward by the frost and it had tipped south. We reset the stone leaving it up about .5 feet.

Description of monument and accessories I established to perpetuate the original location of this corner.  
(field area) (brush land)



NOTE: All trees are blazed and have P.K. nails set in them.



Dated at Merrill, Wis., this 6 day of October, 19 80.

Signature Sheridan D. Schwark Title Registered Land Surveyor Registration No. S-1205  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of Lincoln, I hereby certify that the within instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19 \_\_\_\_\_ at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

(Register of Deeds)

By \_\_\_\_\_ Deputy