
U.S. PUBLIC LAND SURVEY MONUMENT RECORD

NOTE: THIS FORM IS INTENDED AND DESIGNED TO FULFILL ALL REQUIREMENTS OF WISCONSIN ADMINISTRATIVE CODE CHAPTER A-E 7.08 U.S. PUBLIC LAND SURVEY MONUMENT RECORD (3) (a)(b)(c)(d)(e)(f)(g)(h)(i). AN ADDITIONAL SHEET MAY BE ADDED IF NECESSARY TO CONFIRM WITH SAID REQUIREMENTS.

(a) CORNER LOCATION:

S1/4 CORNER OF SECTION 8 **TOWNSHIP 33 NORTH** RANGE 5 EAST TOWN OF HARDING COUNTY OF LINCOLN



(b) HISTORY OF ORIGINAL CORNER:


ORIGINAL SURVEYOR: JACKSON L. PRENTICE DATE OF SURVEY: NOVEMBER, 1854

ORIGINAL BEARING TREES: 10" HEMLOCK - S44°E, 9 LKS 13" PINE - N29°E, 26 LKS

(f)(g)(h) DESCRIPTION OF MONUMENT FOUND AT THIS CORNER AND IF IT WAS ACCEPTED STATE ALL EVIDENCE (MATERIAL, TESTIMONIAL, OCCUPATIONAL, PLATS, RECORDS, OTHER MONUMENTS) USED AS A BASIS FOR ESTABLISHING LOCATION. IF REESTABLISHING THROUGH LOST CORNER PROPORTIONATE METHODS, INDICATE ALL MONUMENTS, DISTANCES, AND DIRECTIONS USED TO ESTABLISH. INDICATE TYPE OF MONUMENT AND SIGN POST FOUND OR SET.

1854: JACKSON L. PRENTICE SET THE ORIGINAL 1/4 SECTION CORNER POST.

- 1930'S: FRANCIS FOX SET A STONE MONUMENT AND MOUNDED WITH STONE. HE NOTES AN 18" WHITE PINE STUMP S34°E. 2.8'.
- 01/14/2010: I FOUND A 6" SQUARE GRANITE MONUMENT IN GOOD CONDITION MOUNDED WITH STONE APPROXIMATELY 90' SOUTHWEST OF A WOODS TRAIL. I SET A 3/4" DIA. REBAR ALONG THE WEST SIDE OF THE MONUMENT. A PLASTIC POST 1' NORTH OF THE MONUMENT, MADE ONE BEARING TREE AND SET THREE 3/4" DIA. CAPPED REBAR REFERENCE MONUMENTS AS SHOWN BELOW.
- (c)(d)(e) PLAN VIEW OF CORNER WITH TIES TO AT LEAST FOUR WITNESSES. IF IN DISAGREEMENT WITH PREVIOUSLY ESTABLISHED CORNER, SHOW THE DISTANCES BETWEEN THE TWO CORNERS AND ALSO INDICATE THE TIE TO THE DISPUTED CORNER.



SIGNATURE

SOUTH ¼ CORNER, SECTION 8 – 6" SQUARE GRANITE STONE FOUND



FACING NORTH



FACING SOUTH



FACING EAST



FACING WEST

