U.S. PUBLIC LAND SURVI	ET MONOWENT RECORD
Note: This form is intended and designed to fulfill a Chapter A-E 5.02, U.S. Public Land Survey (I). An additional sheet may be added if necessary	Monument Record (3) (a) (b) (c) (d) (e) (f) (g) (h)
(a) Corner location: Township 33 North	N
Range6 East	
Town/ City/Village ROCK FALLS	
CountyLincoln	
Sou	th ½ corner, Section 27
accepting. If not acceptted or if nothing was	cords, other monuments) used as a basis for found, state evidence used as basis for the lost corner proportionate methods, indicate all
Corner was set by Francis Fox during According to notes by Fox the corner seroads with offset pipe 24.75' south of We found at the corner location a 3/4" described. Dug with Lincoln County back found 6" x 6" blue granite monument shoulder. Corner falls 10.7 feet south	t was stone monument at intersection of stone. ' iron pipe south of the road as notes hoe 24.75 feet north of iron pipe and with polished top 1.5 feet below road of centerline of Tug Lake Road.
Set 3/4" x 24" iron pipe on south side	MECEIVED AT LINCOLN COOK
	COURTHOUSE THIS IST DAY
	OF
	LAND INFORMATION OFFICE
(c) (d) (e) Plan view of corner with ties to at least 4 previously established corner, show the distate the ties to the disputed corner.	witness monuments. If in disagreement with ances between the two corners and also indicate
rebar set at base of slope	rebar set 5' south of group of 8" Oak
Detail of top of stone TUG	O Set 7/8"x30" iron rebar with Lincoln County cap Existing 3/4" iron pipe LAKE ROAD
South 4 corner 6"x6" granite mon.	(2669.30') 2673.63' N89°19'07"E
rebar set 6' NE of	
two 4" Balsam 0.5' no of orange su	and the second s
(!) I, David J. Goslin RLS No. 2280	
(type or print name) certify that the corner location	n on this record was determined
by me or under my direction and control and that	this U.S. Public Land Survey
Monument Record is correct and complete to the	best of my knowledge and belief.
Caved y. Doslin	1-28-00
Signature	Date

5

Date









