CERTIFIED LAND CORNER RESTORATION

Index No. U-13

History of original corner establishment:

Surveyor: Jackson L. Prentice

Date: December 1854

Monumentation: Wood Post

Witnesses: 10" Spruce, S44° W, 25 lks.
12" Pine, N 69° W, 41 lks.
12" Pine, N 33° E, 63 lks.
10" Birch, S 47° E, 20 lks.

Description of corner evidence found:

A 6" \times 6" \times 30" concrete marker, broken in two pieces, for corner, with a 1" iron pipe on the easterly side. 6" square wood post as reference being Northwesterly of corner.

Description of monument and accessories I established to perpetuate the original location of this corner.

Berntsen Monument - 30"

3/4" iron pipe, N 89° E, 36.63' 3/4" iron pipe, S 1° W, 31.46' 3/4" iron pipe, N 89° W, 30.10' 3/4" iron pipe, N 8° W, 50.79'

Dated at Tomahawk	, Wis., this	8th	day of	June	
Signature Guste John (County Surveyor, Re	Title	Land Sur	veyor	Registra	tion No. S-1192
Office of Register of Deeds, County instrument was filed in this office for	v of			I hereby certi	fy that the within
ato'clock					
(Register of	Deeds)				