## U.S. PUBLIC LAND SURVEY MONUMENT RECORD

NOTE: THIS FORM IS INTENDED AND DESIGNED TO FULFILL ALL REQUIREMENTS OF WISCONSIN ADMINISTRATIVE CODE, CHAPTER A-E 7.08, U.S. PUBLIC LAND SURVEY MONUMENT RECORD (3)(a)(b)(c)(d)(e)(f)(g)(h)(i). ADDITIONAL SHEETS MAY BE NECESSARY TO CONFORM TO SAID REQUIREMENTS.

## (a) CORNER LOCATION:

SOUTH QUARTER CORNER, SECTION 11 TOWNSHIP 35 NORTH RANGE 5 EAST TOWN OF WILSON

LINCOLN COUNTY WISCONSIN

(b) HISTORY OF ORIGINAL CORNER:


ORIGINAL SURVEYOR: Joseph H. Jenkins, Set Post

COMMENCING DATE: September 25, 1862 COMPLETION DATE: October , 1862

**ORIGINAL BEARING TREES:** 

Tamarack; N 85° W; 105 links

5" Tamarack; S 38° W; 108 links



(f)(g)(h) DESCRIPTION OF MONUMENT FOUND AT THIS CORNER AND IF IT WAS ACCEPTED. STATE ALL EVIDENCE (MATERIAL, TESTIMONIAL, OCCUPATIONAL, PLATS, RECORDS, OTHER MONUMENTS) USED AS A BASIS FOR ESTABLISHING LOCATION. IF RE-ESTABLISHING THROUGH LOST CORNER PROPORTIONATE METHODS, INDICATE ALL MONUMENTS, DISTANCES, AND DIRECTIONS USED TO ESTABLISH. INDICATE TYPE OF MONUMENTS FOUND OR SET.

1930's Fancis Fuchs(Fox) found wood post and set Granite Monument.

2/21/2023, I, Anthony R. Dallman, PLS-2405, found a 6" X 6" Granite Monument, up 13". I accepted this location and set witness monuments, as shown in the sketch below, to further perpetuate the corner location.

(c)(d)(e) PLAN VIEW OF THE CORNER WITH TIES TO AT LEAST FOUR WITNESSES. IF IN DISAGREEMENT WITH PREVIOUSLY ESTABLISHED CORNER, SHOW THE DISTANCES BETWEEN THE TWO CORNERS AND ALSO THE TIES TO THE DISPUTED CORNER.

