


CERTIFIED LAND CORNER RESTORATION

Index No. I-19

State of Wisconsin }
County of Lincoln } ss.

I Lester J. Schmit, do hereby certify that on the 12th day of October, 1976, I found evidence of the South 1/4 corner of Section 11 Township 35, North, Range 6 East, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:



○ = Corner monument restored.

History of original corner establishment:

Surveyor: Alfred Millard
Date: 21 October 1860
Monumentation: Wood Post
Witnesses: White Pine 5; N 85° W; 189 links
Yellow Pine 5; S 42° E; 77 links

Description of corner evidence found: 1" iron pipe and scribed wood post.
P.K. Nail in 8" Jack Pine; N 18°30'48" W; 9.14'

Description of monument and accessories I established to perpetuate the original location of this corner.

Berntsen Monument - 30" (set 1" above ground)

P.K. Nail in 10" Jack Pine; N 32°30'02" E; 14.18'
P.K. Nail in 11" Jack Pine; S 67°01'31" E; 8.55'
P.K. Nail in 8" Jack Pine; S 28°17'02" W; 11.01'

Dated at Tomahawk, Wis., this 2nd day of March, 1978

Signature Lester J. Schmit Title Land Surveyor Registration No. S-1192
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy


CERTIFIED LAND CORNER RESTORATION

Index No. I-19

State of Wisconsin }
County of Lincoln } ss.

I Lester J. Schmit, do hereby certify that on the 12th day of October, 1976, I found evidence of the South 1/4 corner of Section 11 Township 35, North, Range 6 East, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:



○ = Corner monument restored.

History of original corner establishment:

Surveyor: Alfred Millard
Date: 21 October 1860
Monumentation: Wood Post
Witnesses: White Pine 5; N 85° W; 189 links
Yellow Pine 5; S 42° E; 77 links

Description of corner evidence found: 1" iron pipe and scribed wood post.
P.K. Nail in 8" Jack Pine; N 18°30'48" W; 9.14'

Description of monument and accessories I established to perpetuate the original location of this corner.

Berntsen Monument - 30" (set 1" above ground)

P.K. Nail in 10" Jack Pine; N 32°30'02" E; 14.18'
P.K. Nail in 11" Jack Pine; S 67°01'31" E; 8.55'
P.K. Nail in 8" Jack Pine; S 28°17'02" W; 11.01'

Dated at Tomahawk, Wis., this 2nd day of March, 1978

Signature Lester J. Schmit Title Land Surveyor Registration No. S-1192
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy