O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION

Index No. U-13

History of original corner establishment:

Surveyor: Alfred Millard

Date: 8 August 1860

Monumentation: Wood Post

Witnesses: 16" White Pine, S 11° E, 25 links 16" White Pine, N 39° E, 20 links

Description of corner evidence found:

A 1" iron pipe & a rotted off wood post for corner location. Witnessed by a 10" Norway Pine, S 35° E, 4.42'
11" Norway Pine, S 87° W, 12.04'

Description of monument and accessories I established to perpetuate the original location of this corner.

Replaced the iron pipe with a 30" Berntsen monument for the corner.

New witnesses: 17" Norway Pine, N 4° E, 15.14'

14" Norway Pine, N 73° E, 21.20'

Dated at Tomahawk ,	Wis., this.	41	th	day of	August	1980
Signature Leveley J. Schmid (County Surveyor, Registered	Title Land Surve	Land	Surve	eyor	Reg	istration No. S 1192
Office of Register of Deeds, County of instrument was filed in this office for recorat					T 1 1	

(Register of Deeds)						